

Report #539093

1954 Chevrolet 3100



Summary

I have inspected this 1954 Chevrolet 3100 and made note of any issues I found below.

Exterior

There are light scratches present around the exterior of the vehicle that are considered normal with age, most are too small to see in photos. The underside shows areas of minor surface rust. See pictures. The wood underneath the bed is starting to deteriorate. I checked the vehicle with a magnet and found it to stick all around but was weaker in the lower panels. Not excessive. The exterior lighting functions as designed.

Interior

The seats show a light amount of wear consistent with the age of the vehicle. The inner door panels show light wear consistent with the age of the vehicle. The interior trim shows light wear considered normal for age. The carpet shows a light amount of wear that is considered normal for the age of the vehicle.

Moving my inspection to focus on the mechanical components of the vehicle, I did not observe any signs of leaks or seepages present from the underside of the vehicle. Looking under the hood I observed that the vehicle's accessible fluids are at their proper level and are a healthy color. All four tires are an appropriate size for the vehicle and show an even wear pattern.

I found no issues on the test drive. The engine had plenty of power and there were no misfires or smoking. The transmission worked as designed. The steering was responsive and the suspension was firm and the vehicle handled well. There were no abnormal vibrations or odd noises. The brakes were firm with no pulsation felt.

See below and pictures for more info.












Vehicle Information

Year	1954
Make	Chevrolet
Model	3100
VIN	N/A
Stock No.	N/A
Mileage	99081
Interior Color	Black
Interior Material	Leather
Engine Cylinders	8 Cylinder
Exterior Color	Blue
Engine Number	N/A
Transmission Number	N/A
Fuel Type	Gas




Drivetrain

Transmission	Manual
Drive Type	Rear Wheel Drive




Road Test

Road Test	 Good
Engine Starting Easily	 Good
Engine running well after Started	 Good
Transmission performance	 Good
Clutch Performance	 Good
Differential Performance	 Good
Transfer Case Performance	 Good
Wheel Bearing Performance	 Good
Braking Performance	 Good
Suspension Performance	 Good
Steering Performance and Alignment	 Good


Exterior

Wiper Blades	 Good
Body Panel Alignment	 Good
Scratches	 Issues






There are light scratches present around the exterior of the vehicle that are considered normal with age, most are too small to see in photos.

Paint Condition	 Good
Seals	 Good
Rust	 Issues




The underside shows areas of minor surface rust. See pictures. The wood underneath the bed is starting to deteriorate.

Exterior Lights	 Good
Power Door Mirrors	 Good
Bumpers	 Good
Side Moldings	 Good
Underbody/Frame Condition	 Good
Glass	 Good
Floors	 Good
Rockers	 Good
Quarter Panels	 Good
Body Filler Used	 Issues





I checked the vehicle with a magnet and found it to stick all around but was weaker in the lower panels. Not excessive.

Hood	 Good
Doors	 Good
Dings	 Good
Dents	 Good
Chrome	 Good





Interior

Steering Wheel	 Good
Horn	 Good
Seat Condition	 Issues










The seats show a light amount of wear consistent with the age of the vehicle.

Seat Belts	 Good
Clock	 Good
Radio/Navigation/DVD	 Good
Inner Door Panels	 Issues

The inner door panels show light wear consistent with the age of the vehicle.

Center Console	 Good
Dash	 Good
Dash Lights Working	 Good
Carpet	 Issues

The carpet shows a light amount of wear that is considered normal for the age of the vehicle.

Floor Mats	 Good
Signs of Smoking?	 Good
Cup Holders	 Good
Headliner	 Good
Blower Motor	 Good
Instrument Cluster/Gauges	 Good
Unusual Odors	 Good
Window Function	 Good
Interior Trim	 Issues

The interior trim shows light wear considered normal for age.

Sun Visors	 Good
------------	--

Mechanical

Engine Oil Leaks	■ Good
Transmission Fluid Leaks	■ Good
Brake System Condition	■ Good
Brake Fluid Leaks	■ Good
Transfer Case Leaks	■ Good
Differential leaks	■ Good
Muffler System	■ Good
CV Boots and Joints	■ Good
Shocks and bushings Condition. Leaking?	■ Good
Ball Joints and Tie Rods	■ Good
Coolant Leaks	■ Good

Tire / Wheels

Manufacturer

Driver's Front Tire	Mastercraft
Passenger's Front Tire	Mastercraft
Driver's 1st Axle Outer Tire	Mastercraft
Passenger's 1st Axle Outer Tire	Mastercraft

Size

Driver's Front Tire	255/70/16
Passenger's Front Tire	255/70/16
Driver's 1st Axle Outer Tire	255/70/16
Passenger's 1st Axle Outer Tire	255/70/16

Tire Condition

Driver's Front Tire	No Issues
Passenger's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues

Wheel Condition

Driver's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's Front Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues

Tire Tread

Driver's Front Tire	11/32
Passenger's Front Tire	11/32
Driver's 1st Axle Outer Tire	11/32
Passenger's 1st Axle Outer Tire	11/32

Spare Tire


No


Vehicle Images











































































































Explore maintenance, repair and inspection services here.

