

## THE SECURITY INDUSTRY STANDARD

## Strong Poles Fly-Out / Fly-Over Pedestal Mount

## **Installation Instructions**

## **Package Includes:**

- 1 4" x 4" x 7.5" Pedestal
- 4 8" x 3/8" Bolts
- 4 3/8-16 x 5/8-1 Thread inserts
- 3 1-1/2" Cap plug
- 6 #18 Cap Plug
- 2 1/8" Self Drilling Top Attachment csrews
- 1 Gasket
- 1 Plastic Pedestal top



- 1. 4 Threaded Inserts need to be installed using wide blade screwdriver, flush in pole top threads.
- 2. Attach Pedestal using the four 8''x 3/8 bolts in the thread adaptors using the gasket between the pole top and pedestal.
- 3. Attach Fly-Out(s) of Fly-Over to the pedestal and connect wiring.
- 4. Install cap plugs in unused openings to stop water and dust from Entering.
- 5. Install top Cap using 1/8" Self Drilling Screws.

