

Showbits (32 bits)

CLZ

leading
zeros < 16

No

Arithmetic
operation

Yes

Leading zeros table
mapping

Skipbits (leading zero+1)

Getbits (remainder bits)

Coefficient table
mapping

Skipbits (remainder bits)