




GUIDE TO ASSEMBLY



TO TIGHTEN CORNERS

Use the spanner to tighten each corner connector as shown:

